



Inventor: Tsang
Docket No.: 12608.0004US11
Title: C-I-P OF TOY STEERING DEVICE
Serial No.: 10/047473
Sheet 1 of 13

BEST AVAILABLE COPY




FIG -1

OCT 27 2004





FIG - 2



Inventor: Tsang
Docket No.: 12608.0004US11
Title: C-I-P OF TOY STEERING DEVICE
Serial No.: 10/047473
Sheet 3 of 13





FIG-3

OCT 27 2004



FIG - 4





Inventor: Tsang
Docket No.: 12608.0004USII
Title: C-I-P OF TOY STEERING DEVICE
Serial No.: 10/047473
Sheet 5 of 13




FIG-5



Inventor: Tsang
Docket No.: 12608.0004US11
Title: C-I-P OF TOY STEERING DEVICE
Serial No.: 10/047473
Sheet 6 of 13




FIG-6




FIG-7



Inventor: Tsang
Docket No.: 12608.0004US11
Title: C-I-P OF TOY STEERING DEVICE
Serial No.: 10/047473
Sheet 7 of 13




FIG - 8




FIG - 9



Inventor: Tsang
Docket No.: 12608.0004USII
Title: C-L-P OF TOY STEERING DEVICE
Serial No.: 10/047473
Sheet 8 of 13




FIG-10





FIG-11

Figure 12






Figure 14

214

Figure 13




Figure 15




Figure 16







Figure 17






FIG -18

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER: _____**

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.